

RTCA, Inc.
1828 L Street, NW, Suite 805
Washington, D.C. 20036-5133 USA

**Report – Assessment and Recommendations on
Visual Alerts and Aural Annunciations for
TCAS II**

RTCA DO-299
March 14, 2006

Prepared by: SC-147
© 2006 RTCA, Inc.

Copies of this document may be obtained from

RTCA, Inc.

Telephone: 202-833-9339

Facsimile: 202-833-9434

Internet: www.rtca.org

Please visit the RTCA Online Store for document pricing and ordering information.

FOREWORD

This document was prepared by RTCA Special Committee 147 (SC-147) and approved by the RTCA Program Management Committee (PMC) on March 14, 2006.

RTCA, Inc., is a not-for-profit corporation formed to advance the art and science of aviation and aviation electronic systems for the benefit of the public. The organization functions as a Federal Advisory Committee and develops consensus based recommendations on contemporary aviation issues. RTCA's objectives include but are not limited to:

- coalescing aviation system user and provider technical requirements in a manner that helps government and industry meet their mutual objectives and responsibilities;
- analyzing and recommending solutions to the system technical issues that aviation faces as it continues to pursue increased safety, system capacity and efficiency;
- developing consensus on the application of pertinent technology to fulfill user and provider requirements, including development of minimum operational performance standards for electronic systems and equipment that support aviation; and
- assisting in developing the appropriate technical material upon which positions for the International Civil Aviation Organization and the International Telecommunication Union and other appropriate international organizations can be based.

The organization's recommendations are often used as the basis for government and private sector decisions as well as the foundation for many Federal Aviation Administration Technical Standard Orders.

Since RTCA is not an official agency of the United States Government, its recommendations may not be regarded as statements of official government policy unless so enunciated by the U. S. government organization or agency having statutory jurisdiction over any matters to which the recommendations relate.

This document contains copyrighted material that is reproduced with permission from the respective copyright holders - The Boeing Company, Airbus SAS, and Honeywell International, Inc.

Inquiries regarding this material may be made to:

The Boeing Company
15460 Laguna Canyon Road
Irving, CA 92518

Airbus SAS
316 route de Bayonne
31060 Toulouse Cedex 03
France

Honeywell International, Inc.
Aerospace Intellectual Property
PO Box 97001
15001 NE 36th St
Redmond, WA 98073



This Page Intentionally Left Blank

EXECUTIVE SUMMARY

Background and Data

Monitoring of TCAS performance has identified instances where flight crews responded in the opposite direction to that specified by TCAS when a resolution advisory (RA) was displayed and announced to the flight crews. Many of these opposite responses were observed for RAs classified as Negative RAs by the collision avoidance system (CAS) logic, and are characterized by the fact that the flight crew believed their response was correct, i.e., not opposite. A Negative RA is typically issued when a TCAS-equipped aircraft is climbing or descending towards another aircraft, and the CAS logic determines that the TCAS-desired vertical miss distance between the two aircraft can best be achieved by the TCAS aircraft reducing its vertical speed. These RAs are accompanied by an aural annunciation of 'Adjust Vertical Speed, Adjust' (AVSA). The proper response to a Negative RA is always a reduction in vertical speed, i.e., a maneuver towards level flight. When a flight crew maneuvers in the opposite direction to a Negative RA, it is almost always maneuvering towards the intruder and thus reducing rather than increasing the vertical miss distance with the other aircraft. Such an opposite response represents a safety issue.

Because opposite reactions to Negative RAs have been regularly identified since the introduction of TCAS II, and have continued since the introduction of TCAS II Version 7, RTCA Special Committee 147 (SC-147) was tasked to perform studies and analyses to investigate the display configurations and aural alerts used for Negative RAs. The purpose of these investigations was to determine whether any problems exist with the current requirements for displaying and annunciating this class of RAs. The SC-147 requested that its Operations Working Group (OWG) investigate this issue and provide a report that documents whether any problems exist in the current requirements for displaying and annunciating Negative RAs and if so, to recommend an approach to resolving the identified problem(s).

Note: The focus of the OWG's investigation has been on opposite responses to initial Negative RAs and all references to 'Negative RAs' in this Executive Summary and this Report are for initial Negative RAs.

The OWG has reviewed data from multiple sources during its investigation of this issue and has used these data to develop a number of near term and longer term recommendations. Data have been obtained from:

- Operational monitoring programs using radar data, pilot questionnaires, and controller questionnaires
- Formal investigations of some opposite responses conducted by State's accident investigation organizations
- Dedicated simulations to collect data on pilot response to Negative RAs
- On board data recordings and airline safety reporting systems

The available data have yielded the following results:

1. There have been opposite responses to Negative RAs that have resulted in the separation between the aircraft involved in the encounter becoming unacceptably small, including one event involving issue SA01 as described in DO-298.

-
- A. The majority of these opposite responses have occurred on aircraft where RA visual guidance is only provided on a limited analog range vertical speed indicator. Opposite responses have occurred at a significantly higher rate for Negative RAs requiring a reduction in vertical speed to 500, 1000, or 2000 feet per minute (fpm) when using these displays. Only a limited number of opposite responses to Negative RAs requiring a level off, i.e., a reduction in vertical speed to zero fpm, have been observed. The same aural annunciation is used for all Negative RAs.
 - B. The recorded opposite responses that have resulted in unacceptable separation between aircraft have occurred in Europe. While opposite responses to Negative RAs have been observed in U.S. airspace using radar data, there have been no events identified in over 1500 controller questionnaires received during 2005 where such a response resulted in a loss of standard air traffic control separation between aircraft. In spite of this, it is believed that additional monitoring using on board data recording will identify events where a loss of separation has occurred.
2. Three primary causes for opposite responses have been identified:
 - A. **Lack of suitable training.** Many training programs do not include simulations of Negative RAs nor include specific instructions on the expected response to Negative RAs. In some incidents where there was an opposite response to the RA, the pilots had never before encountered a Negative RA.
 - B. **Limitations in the aural annunciations.** The “Adjust Vertical Speed, Adjust” aural annunciation does not provide complete information on what a pilot has to do to comply with the RA. This is inconsistent with all other aural annunciations for corrective RAs, which explicitly state the corrective action to be taken by the flight crew.
 - C. **Difficulty in interpreting displays.** The large majority of misinterpretations took place with highly nonlinear vertical speed displays to provide RA guidance. Multiple display issues have been identified on one implementation, including: vertical speed needle visibility; limited analog range on some displays; and discrimination and understanding of red and green regions. Monitoring data have not identified any opposite responses to Negative RAs that require the TCAS aircraft to be leveled off, which strongly suggests that the display is a factor, since the aural annunciation is the same for all Negative RAs.

The above three primary causes appear to be interrelated, such that their combination needs to be considered in any analysis or proposed solution. At present the OWG considers that there is insufficient data to know how changing each of these factors affects the likelihood of an opposite response to a Negative RA, and therefore further research into these primary causes is recommended.

The OWG has also identified some secondary causes that could warrant further investigation:

- *Language.* Non native English speakers have been involved in nearly all the known opposite responses to Negative RAs that resulted in unacceptable separation between aircraft. It is noted that the word “Adjust” contains no information on the sense, or direction, of the required response to the RA.
- *Procedures.* Variations in procedures (such as switching off the FD during an RA) may affect how well Negative RAs are followed
- *Visual acquisition.* Visual perception errors, in combination with the lack of directional information in the aural annunciation used for Negative RAs may lead to opposite responses.

Conclusions and Recommendations

Opposite responses to Negative RAs can result in less than desired separation from other aircraft and is thus considered to be a safety issue.

Based on the work completed to date, the OWG has reached the following conclusions and recommends that the following actions be undertaken by RTCA and the organizations supporting the work of SC-147 and the OWG.

Training

Enhanced emphasis on the expected response to Negative RAs during pilot training and providing information to pilots describing the effects of an opposite response has been demonstrated to decrease, but not eliminate, the number of opposite responses to Negative RAs. The OWG recognizes that training should not be relied on to overcome any design weaknesses in a system. However, based on demonstrated experience that increased attention to the proper response to Negative RAs will reduce the occurrence of opposite responses, the OWG is recommending that all pilots receive training on the expected response to Negative RAs during their TCAS maneuver training. Wherever possible, this training should be conducted in a flight simulator.

To support this recommendation, the report contains information that can be disseminated to operators that describe the expected response to RAs. This information should have the widest possible distribution. The report also provides updated guidelines for TCAS training and these should also be distributed as widely as possible within the next three months.

The OWG recognizes that without guidance on how to set up a scenario that consistently results in a Negative RA being issued, it is unrealistic to expect simulator instructors to train pilots on the expected response to Negative RAs. To support this, it is recommended that SC-147 perform the work necessary to provide operators and simulator instructors with guidance on generating Negative RAs during a flight. This guidance would define encounter parameters for selected weight, altitude, temperature, and aircraft state that could be entered to cause Negative RAs to be issued. This information would be required for multiple aircraft types and would require work to establish the parameters for these aircraft types. It is estimated that this information could be available for distribution within a six month period.

As a longer term action, the OWG recommends that its future work program include a task to provide an assessment of the effectiveness of the revised training guidelines and explicit guidance on expected response to Negative RAs in reducing the frequency of opposite responses to these RAs.

Aural Annunciations

The OWG has noted that several European organizations have concluded that the lack of directional information in the aural annunciation “Adjust Vertical Speed, Adjust” contributes to opposite responses to Negative RAs. The OWG has received requests from Air France and Lufthansa to evaluate alternative aural annunciations to determine whether the use of another annunciation would improve pilot response to Negative RAs.

To be able to respond to these requests, the OWG recommends that evaluations be completed to determine whether the modification of the aural annunciations would be beneficial. These evaluations would assess pilot performance when the “Adjust Vertical Speed, Adjust” annunciation is replaced with another aural annunciation.

The evaluation of these alternative aural annunciations may include the completion of safety studies, TCAS/ATC compatibility analyses, and human factors assessments.

Displays

Opposite responses to Negative RAs are primarily seen on limited analog range vertical speed indicator implementations (vertical speed tapes and partial representations of round dial vertical speed indicators), suggesting that the display is a significant factor. In some specific scenarios these displays are more prone to allowing misinterpretation of Negative RAs. The contribution of displays to the problem may be exacerbated by the lack of sense information in the associated aural annunciation. However, the exact mechanism by which displays affect opposite responses to negative RAs is not well understood.

Assessment is needed of how displays are contributing to the observed problems. If possible, ways of reducing the effects of displays on opposite responses to RAs will be assessed. The OWG is aware that some manufacturers are updating their displays and will continue to follow this work.

Monitoring

The longer term recommendations also include several monitoring tasks. These include expanding operational monitoring to obtain additional information, especially airborne recorded data, to help identify the root cause(s) of opposite responses; monitoring work being done by airframe manufacturers to modify their display implementations; and coordinating any lessons learned from manufacturers’ investigations with other manufacturers. These tasks are structured to provide additional information that will assist the OWG and SC-147 in focusing its resources on other recommended studies and tasks.

Further Comments and Recommendations

A reduction in Negative RAs can likely be achieved if aircraft reduce their vertical speed when approaching an assigned altitude. Data collected by Lufthansa over a one year period showed that the likelihood of receiving an RA while leveling off is three times lower when the vertical speed of a climbing or descending aircraft is reduced to less than 1500 fpm within the last 1000 feet of the climb or descent. Observations made during the simulator data collection noted that approximately 65% of the pilots reduced their vertical speed when climbing or descending towards another aircraft when that aircraft was observed visually, observed on the traffic display, or after the traffic advisory (TA) was issued. Any Negative RAs issued after these reductions in vertical speed reinforced the actions taken by the pilots. The Federal Aviation Administration's Advisory Circular 120-55B currently addresses reducing vertical speed to between 500 and 1500 fpm during the last 2,000 feet of a climb or descent under 'Good Operating Practices'. The ICAO Operations Panel (OPSP) has prepared proposed amendments to Annex 6 and PANS-OPS that contain similar recommendations.

The OWG supports the OPSP recommendations to reduce the vertical speed to a value between 500 and 1500 fpm when within 1000 feet of an assigned altitude when the pilot is aware of traffic at or maneuvering to level at an adjacent altitude. The pilot can become aware of such traffic via visual acquisition of the traffic, from information shown on the traffic display, or from information provided by the controller. It is recommended that this guidance be included in pilot training programs as soon as possible. The longer term solution to this issue, as defined in the draft ICAO guidance material, is to have the autopilot or flight management system incorporate logic that automatically reduces the vertical speed when approaching an assigned altitude. The OWG fully supports this longer term solution for new aircraft and flight control system certifications. The OWG does not believe that retrofitting existing aircraft should be mandatory.

Whilst working on Negative RAs, the OWG has noted another more general issue: there are some inconsistencies in the published procedures that define the expected response to RAs. These inconsistencies exist in both high level guidance material on RA responses from ICAO and States and in detailed procedures contained in operators' training and operations manuals. Since this finding is a by-product of the OWG's work to date, whose purpose was not to review procedures, the OWG recommends that additional, detailed reviews of procedures and guidance for responding to RA, be completed to determine if there are other inconsistencies contained in Training Manuals and Flight Operations Manuals. The OWG would then develop recommendations on changes that should be made to published procedures and guidance, and define what form and type of additional guidance should be given to operators of TCAS equipped aircraft. It is estimated that the completion of this work would require approximately eight months and would require cooperation from operators and manufacturers to allow the review of their publications to be made by the OWG.

The work completed by the OWG has identified several RA display implementations that do not meet the requirements contained in DO-185A. The OWG recommends that the display implementations and the requirements of DO-185A be consistent. This can be accomplished by recommending modifications to existing display systems or if appropriate, modifying the requirements contained in DO-185A. In those cases where discrepancies are noted between implementations and DO-185A requirements, SC-147 should evaluate whether the displays deviating from the DO-185A requirements meet the technical and operational intent of the DO-185A requirements.

If this evaluation determines that the existing implementations meet the intent of the DO-185A requirements, DO-185A should be modified to explicitly permit these implementations to be used by other manufacturers. Should the evaluation determine that the current implementation does not meet the technical and operational intent of the MOPS requirements, the appropriate certification authorities should be provided with information that documents the non-compliance with DO-185A, the concern of the OWG, and a request to review existing implementations to determine if any changes are necessary.

Even when they are understood correctly, and result in the desired action, flight crew can report the RA to the controller in a way that will mislead the controller. For example, an AVS RA to reduce the rate of climb is sometimes reported as “TCAS climb” because a rate of climb is recommended by TCAS and the aircraft is climbing. Where this RA is coordinated, the other aircraft might well have received a climb RA and the pilot of that other aircraft should report “TCAS climb”. The controller then hears “TCAS climb” from both flight crew and, at best, is confused. It is recommended that problems with the phraseology for reporting AVS RAs to the controller be brought to the attention of the FAA.

TABLE OF CONTENTS

1	INTRODUCTION.....	1
1.1	Statement of purpose.....	1
1.2	Background.....	2
1.3	Current Statement of OWG Issues.....	2
1.3.1	Misinterpretation of an Initial Negative RA Leading to an Opposite Response.....	3
1.3.2	Flying Through a Cleared Flight Level Whilst Complying with a Negative RA.....	3
1.3.3	Reducing Separation with the Intruder Whilst Complying with a Preventive RA.....	3
1.4	Factual Description of Workings of TCAS Logic in Encounters Resulting in Negative RAs.....	4
1.5	Structure of the Report.....	5
1.6	Abbreviations and Acronyms.....	6
2	FACTUAL DESCRIPTION OF DISPLAYS.....	9
2.1	Vertical Speed Tape.....	9
2.2	Round-dial IVSI.....	11
2.3	Semi circular vertical speed indicator.....	13
2.4	Pitch Cue Symbol.....	17
3	DATA COLLECTION.....	21
3.1	Method.....	21
3.1.1	Operational Data.....	21
3.1.1.1	How Operational Monitoring is Conducted.....	21
3.1.1.2	Activities in the United States.....	21
3.1.1.3	Activities in Europe.....	22
3.1.1.4	Activities in Japan.....	23
3.1.2	Simulation Data Collection Methodology.....	23
3.1.2.1	Background.....	23
3.1.2.2	Scope.....	23
3.1.2.3	Scenario Description and Data Collection Approach.....	24
3.1.3	Methodology Used to Collect Information on Stress During RAs.....	26
3.1.3.1	Context.....	26
3.1.3.2	Description of the simulations.....	27
3.2	Operational Data Collection Results.....	28
3.2.1	European Results.....	28
3.2.1.1	Incorrect Responses to Other RAs (Initial Corrective, Preventive, Weakening).....	28
3.2.1.2	Description of Planned Modifications to Airbus Displays.....	29
3.2.1.3	Airline Operational Data.....	30
3.2.1.4	Accident Investigation Reports.....	36
3.2.1.5	Pilot and Controller Report Analyses.....	43
3.2.1.6	Synthesis of the results.....	45
3.2.2	Operational Data from the United States.....	47
3.2.2.1	Controller Questionnaires.....	48
3.2.2.2	ATA and Airline Data.....	48
3.2.2.3	Review of ASRS Data.....	49
3.2.2.4	Onboard Data Recording.....	50

3.2.2.5	Mode S Data Recording	50
3.2.3	Japanese Results	53
3.3	Simulation results summary	54
3.3.1	Automatic Data Recording	54
3.3.2	Subject Pilot Debriefing Questionnaires	58
3.3.3	Observations	65
3.3.3.1	Vertical Speed Reduction	65
3.3.3.2	RA Response via Autopilot	66
3.3.3.3	Autothrust Usage	66
3.3.3.4	Flight Director Usage	67
3.3.3.5	Display Readability	67
3.3.3.6	Display Consistency with MOPS Requirements	68
3.3.3.7	Awareness of Intent of Data Collection.....	68
3.4	Main Results of the DSNA Simulation on Stress During RAs	69
3.4.1	Simulation runs and collected data	69
3.4.2	Characteristics of triggered TCAS alerts	70
3.4.3	Heart rate	70
3.4.4	Detected Errors	71
3.4.4.1	Categories of Detected Errors.....	71
3.4.4.2	Reporting of RAs to Controllers.....	71
3.4.4.3	Comments on the “Adjust Vertical Speed, Adjust” Aural Annunciation.....	73
3.4.4.4	Reactions to Negative RAs.....	74
3.4.5	DSNA Report Recommendations	74
4	CONCLUSIONS	75
4.1	A Safety Issue Exists.....	75
4.1.1	Simulation Data	75
4.1.2	Airline Data	75
4.1.3	ACAS Monitoring program Data.....	76
4.1.4	Accident Investigation Data.....	77
4.1.4.1	Identification of Causes	77
4.1.5	Safety issue argument summary	78
4.2	Demonstrated Benefit of Increase Emphasis in Training.....	79
4.3	Other Issues.....	80
4.3.1	Reduction in Vertical Speed Approaching an Altitude.....	80
4.3.2	Inconsistency in Procedures for Responding to RAs.....	81
5	RECOMMENDATIONS	83
5.1	Summary of Recommendations	83
5.2	Recommendations Related to Pilot Training	83
5.2.1	Provide Guidance to Crews on Expected Response to Negative RAs.....	83
5.2.2	Update Pilot Training Guidelines	85
5.2.3	Provide Information that Instructors Can Use to Create Negative RAs in Simulators	87
5.2.4	Evaluate Effectiveness of Updated Training Guidelines	88
5.3	Recommendations Related to Modifying TCAS Displays	89
5.3.1	Investigate Reasons for More Frequent Opposite Responses to Weaker Negative RAs.....	89
5.3.2	Monitor Work on Proposed Modifications to RA Displays	90
5.4	Recommendations Related to Modifying TCAS Aural Annunciations	90
5.4.1	Evaluate Proposed Modification of “Adjust Vertical Speed, Adjust” Aural Annunciation	90
5.4.2	Assess Effects of Native Language on Aural Annunciation Interpretation	92

5.5	Other Issues.....	93
5.5.1	Increased Emphasis on Vertical Speed Reduction Approaching an Altitude.....	93
5.5.2	Review Procedures for Consistency	94
5.5.3	Modify Displays and/or DO-185A	95
5.5.4	Continue with Operational Monitoring.....	96
5.5.5	Coordination with Equipment and Airframe OEMs.....	97
5.5.6	Phraseology for Reporting Negative RAs to Controllers.....	98
MEMBERSHIP		99

TABLE OF APPENDICES

Appendix A	A-1
Appendix B.....	B-1
Appendix C.....	C-1
Appendix D	D-1
Appendix E.....	E-1

TABLE OF TABLES

Table 3-1 Improper Responses in Airborne Recorder Data	50
Table 3-2 Reporting Errors for Negative RAs.....	72
Table 3-3 Examples of Debriefing on Reporting Errors for Negative RAs	72
Table 3-4 Example of Controller/Pilot Debriefing after an Incorrect Report of a Negative RA.....	73
Table 4-1 Number of Opposite Responses to Negative RAs.....	79
Table 5-1 Summary of Recommendations	84
Table B-1 Expected Responses to Some Types of RAs.....	B-9
Table D-1 TCAS Version 7 Aural Annunciations, Conditions Causing the RA, and Expected Response to RA.....	D-4

TABLE OF FIGURES

Figure 1-1 Example of an Opposite Response to an Initial Negative RA	4
Figure 2-1 Vertical Speed Tape with No RA Guidance Displayed.....	9
Figure 2-2 Vertical Speed Tape with Reduce Climb to 1000 fpm RA Displayed.....	10
Figure 2-3 Airbus PFD Showing Compliance with an RA to Reduce Climb to 500 fpm.....	10
Figure 2-4 Airbus PFD Displaying an RA to Reduce Climb to 1000 fpm.....	11
Figure 2-5 Information Displayed on Airbus PFD During an RA	12
Figure 2-6 Climb RA on a Mechanical Round-Dial IVSI.....	13
Figure 2-7 Climb RA on a LCD Round-Dial IVSI.....	14
Figure 2-8 Reduce Climb to 2000 fpm RA on an LCD Round-Dial IVSI	14
Figure 2-9 Semi-circular VSI on a PFD	15
Figure 2-10 Vertical Speed Indicator Example	16
Figure 2-11 Example of Climb RA on VSI.....	17
Figure 2-12 Pitch Cues on PFD with Baseline Split Cue Flight Director Format.....	18
Figure 2-13: Pitch Cues on PFD with Optional Integrated Cue Flight Director Format.....	19
Figure 3-1 Primary Flight Display Showing Modified Elements to Provide RA Guidance	30
Figure 3-2 Poster developed by Air France to catch pilots attention regarding Negative RAs.....	32
Figure 3-3 Opposite reaction to Negative RA on an A320.....	33
Figure 3-4 Opposite reaction to a Negative RA	37
Figure 3-5 Vertical Profile for ERJ 145 Involved in the 2002 UK Event	40

Figure 3-6 Vertical Speed Profile for ERJ 145 Involved in the 2002 UK Event.....	41
Figure 3-7 Altitude Profiles for August 2004 Swedish Event	42
Figure 3-8 Vertical Speed Profile for August 2004 Swedish Event.....	43
Figure 3-9 Opposite reaction to a Negative RA	44
Figure 3-10 Opposite reaction to a Negative RA on a B737-400.....	45
Figure 3-11 Negative and Climb RAs Displayed on a Round-Dial IVSI.....	47
Figure 3-12 Vertical Rate During vs. Prior to Limit Climb RAs	52
Figure 3-13 Vertical Rate During vs. Prior to Limit Descent RAs.....	52
Figure 3-14 Pilot Response to Limit Climb RAs.....	55
Figure 3-15 Pilot Response to Limit Descent RAs.....	57
Figure 3-16 Pilot Response to Positive RAs.....	58
Figure 3-17 Subject Pilots' Assessment of Simulation Realism	59
Figure 3-18 Subject Pilots' Assessment of Ease in Interpreting Required Actions Following Initial, Negative RA.....	60
Figure 3-19 Subject Pilots' Assessment of Ease in Interpreting Required Actions Following Initial, Climb or Descend RA Followed by a Weakening RA	61
Figure 3-20 Subject Pilots' Assessment of Usefulness in Determining Required Actions Following Initial, Negative RA	62
Figure 3-21 Subject Pilots' Assessment of Usefulness in Determining Required Actions Following Initial, Climb RA Followed by a Weakening RA	63
Figure 3-22 Subject Pilots' Assessment of Usefulness in Determining Required Actions Following Initial Descend RA Followed by a Weakening RA	63
Figure 3-23 Example of Display Where Digital Indication of Vertical Speed Overwrites Portion of the Red Zone on the Vertical Speed Tape	65
Figure 3-24 Example of Vertical Speed Needle Obscuring the Break Between the Red and Green Zones on the Vertical Speed Tape.....	68
Figure 3-25 Example of PNF Heart Rate during a Climb RA.....	70
Figure 3-26 Distribution of detected errors	71
Figure B-1 CRJ Passing Through the Cleared Flight Level When Correctly Reacting To VSL RA.....	B-2
Figure B-2 Falcon 2000 Passing Through The Cleared Flight Level When Correctly Reacting To Negative RA.....	B-4
Figure B-3 RA Pitch Cue Display For Preventive RA with Intruder 500 Ft Below, Boeing 737-800.....	B-5
Figure B-4 Inappropriate Reaction To Preventive RA, Boeing 737-800	B-6
Figure B-5: Weakening RA displayed with pitch cue and on round-dial IVSI.....	B-7
Figure B-6: Preventive RA Displayed With Pitch Cue and Round-Dial IVSI.....	B-7
Figure B-7 Preventive and Negative RAs with RA Pitch Cue Display Aural Message, Displayed RA Information and Expected Response	B-11
Figure B-8 Red Zone and Green Zone on Vertical Speed Tape Have the Same Width.....	B-12
Figure B-9 Green Zone Removed from Vertical Speed Tape After Complying with a Negative RA	B-13
Figure B-10 Vertical Speed Tape Indication for Weakening RA After a Climb RA	B-14

1 INTRODUCTION

1.1 Statement of purpose

Monitoring of TCAS performance has identified instances where flight crews responded in the opposite direction to that specified by TCAS when the resolution advisory (RA) was displayed to the flight crews. These opposite responses were observed for RAs classified as Negative RAs by the collision avoidance system (CAS) logic, and are characterized by the fact that the flight crew believes their response is correct, i.e., not opposite. A Negative RA is typically issued when a TCAS-equipped aircraft is climbing or descending towards another aircraft, and the CAS logic determines that the TCAS-desired vertical miss distance between the two aircraft can best be achieved by the TCAS aircraft reducing its vertical speed. Negative RAs are also referred to as Adjust Vertical Speed, Adjust (AVSA) or Vertical Speed Limit (VSL) RAs. The terms “Negative RA”, “AVSA RA”, and “VSL RA” are used interchangeably in this report. The focus of this report is on Negative RAs that are issued as the initial RA received during an encounter. All references to “Negative RAs” should be interpreted as referring to initial Negative RAs.

In these types of encounters, TCAS can issue RAs that call for the existing vertical speed to be reduced to a value less than 2000, 1000, 500, or to 0 feet per minute (fpm). These RAs are accompanied by an aural annunciation of “Adjust Vertical Speed, Adjust”. The proper response to a Negative RA is always a reduction in vertical speed, i.e., a maneuver towards level flight. When a flight crew maneuvers in the opposite direction to a Negative RA, it is maneuvering towards the intruder and thus reducing rather than increasing the vertical miss distance with the other aircraft. Such an opposite response represents a safety issue. Although the Operations Working Group (OWG) has not developed a standard definition of an opposite response, the OWG has agreed that responses with a sustained and noticeable change in vertical speed that is opposite to the RA sense is required to classify the response as an opposite response. Different organizations supporting the OWG have defined their own criteria to complete their analyses.

If an opposite response results in continued vertical convergence between two aircraft, the TCAS logic will strengthen the initial Negative RA by issuing either a stronger Negative RA or a Climb or Descend RA, as appropriate. A Climb RA is considered an “up-sense” advisory and would be issued if the response to a Negative RA calling for a reduction in descent rate is not achieving the TCAS-desired separation. A Descend RA would be issued in cases where the initial Negative RA called for a reduction in climb rate.

Because opposite reactions to Negative RAs have been regularly identified since the introduction of TCAS II, and have continued since the introduction of TCAS II Version 7, RTCA Special Committee (SC) 147 was tasked to perform studies and analyses to investigate the display configurations and aural alerts used for Negative RAs. The purpose of these investigations was to determine whether any problems exist with the current requirements for displaying and annunciating this class of RAs. SC-147 requested that the OWG investigate this issue and provide a report that documents whether any problems exist in the current requirements for displaying and annunciating Negative RAs and if so, to recommend an approach to resolving the identified problem(s).